

SERVICE/MAINTENANCE/REPAIR HISTORY

1992 BMW E34 M5 black/black
WBSHD931XNBK06320

Jun? 2017 – 176500? Miles
Roper Mountain Auto Care, Greenville SC
> Sunroof interior trim panel re-attached.
> Oil, filter, fluids.

Jul 2016 – 174903 miles
Euro-Sports, Spartanburg SC
> New AC compressor, dryer and evacuator.
> New auxiliary fan relay.
> Replaced fog light bracket.

Jul 2016 – no mileage recorded
Fairway Auto Body, Greenville SC (master certified BMW body repair facility)
> Repair of roof dent over right front passenger door and LR quarter panel parking dent.

Jan 2016 – 173222 miles
Import Autowerks, Braintree MA
> Battery cut-off switch installed.
> Fuel-tank straps replaced.
> Fluid levels checked and topped up.

Jan to May 2016
Car in storage at Import Autowerks, Braintree MA.

Oct 2015 – 172573 miles
Import Autowerks, Braintree MA
> New drive belts.
> New brake light switch.

Aug 2015 – 172573 miles
Import Autowerks, Braintree MA
> Oil, filter, fluids.
> New oil level sender.
> New window switch.
> New sill strips R front and R rear.
> Rear brakes, incl new disks.
> Trunk and R front rubber moldings replaced.
> New climate control ECU, ambient temp sensor and cabin air filter.
> New window washer nozzles.
> New headlights.
> Replace R rear marker assembly.
> Throttle linkage lubricated.

Sometime during the year of 2014 – no mileage or invoice record

> MAF sensor unit refurbished and recalibrated by Injection Labs, Colorado. Removal and re-installation performed by Import Autowerks, Braintree MA.

Apr 2014 – 170820 miles

Import Autowerks, Braintree MA

> Oil, filter, fluids.

Dec 2013 – 169264 miles

Import Autowerks, Braintree MA

> Oil, filter, fluids.

> New strut inserts installed to moderate ride harshness.

> Door lock tabs adjusted to equalize height.

> New brake light switch.

Sep 2013 – 166701 miles

Import Autowerks, Braintree MA

> O₂ sensor control checked; o-ring and hose replaced.

Jul 2013 - 165734 miles

Import Autowerks, Braintree MA

> Replaced auxiliary fan relay assembly.

Jul 2013 – 165632 miles

Import Autowerks, Braintree MA

> Driver seat back mechanism repaired.

Jun 2013 – 165273 miles

Import Autowerks, Braintree MA

> All four wheels re-finished, new cap emblems.

> New OEM BMW radiator, new fan shroud, new radiator hoses.

> New battery.

May/Jun 2013 – 160693 miles

Imperial Auto Body, Wilmington MA

> Complete body refurbishment.

> Sanded down to primer.

> Glass-out re-paint in black Glasurit, including door jambs.

> New OEM BMW front fenders.

> Four rust free doors from 1994 E34 540

> New windshield.

> New door and window rubber seals.

> Front air dam refurbished.

Dec 2012 – 164242 miles

Import Autowerks, Braintree MA

> Oil, filter, fluids.

> New window regulator.

> Oil pan gasket replaced.

Jul 2012 – 160693 miles
Import Autowerks, Braintree MA
> New hood struts.

May 2012 – 160693 miles
Import Autowerks, Braintree MA
> Oil, filter, fluids
> Fuel lines replaced.
> Replaced water pump.
> Conforti chip installed.

Sep 2011 – 154400 miles
Import Autowerks, Braintree MA
> Oil, filter, fluids.
> Valve adjustment.
> Front distributor seal replaced.
> Rear cylinder head gasket seal replaced.
> Replaced cam housing gasket.
> Replaced valve cover gasket set and seal.
> Replaced cam seal and cam guide o-ring.
> New distributor rotor and cap.
> Repaired RF passenger door lock.
> Replaced a/c condenser, condenser/dryer and pressure hose.

Apr 2011 – 151544 miles
Import Autowerks, Braintree MA
> New alternator.

Jan 2011 – 156054 miles
Import Autowerks, Braintree MA
> R rear brake light bulb replaced.
> Battery check and re-charge.

Latter half of 2010 – no mileage or receipts available
Import Autowerks, Braintree MA
> H&K/Bilstein SLS delete suspension system was installed.

2007 through early 2010 - Cannot locate service records for this period.
> Periodic oil, filter, fluid service at local garage in Hyannis MA while actually on the road.
> Car sat idle in garage storage for approximately two years (08-09).

Nov 2006 – no mileage recorded
Service provider not recorded
> HVAC condenser and Receiver/dryer replaced.

Nov 2006 – 137831 miles
Enginuity Inc, Dennis MA
> Hydraulic lines replaced.

Oct 2006 – no mileage recorded
Enginuity Inc, Dennis MA
> Drive belts replaced.
> Injectors removed and cleaned.

Sep 2006 – no mileage recorded
Enginuity Inc, Dennis MA
> Oil service
> Replaced intake boot.
> New gas flap
> Replaced front sway bar link
> Replaced upper thrust arms
> Replaced center link and tie rod assemblies.
> New front rotors and pads
> Throttle bodies disassembled, cleaned, linkages lubricated and adjusted.
> New battery.

2004-2005

Service records for period not retained: periodic (approximately 5000 mile intervals) oil, filter, fluids service by local garage.

Oct 2003 – 100220 miles
Foreign Motors West, Natick MA
> Oil, filter, fluids.
> Replaced valve cover gasket.
> New spark plugs, distributor cap and rotor.
> L front marker light housing replaced.

Aug 2002 – 86556 miles
Foreign Motors West, Natick MA
> Accessory drive belts replaced.

Apr 2002 – 80840 miles
Foreign Motors West, Natick MA
> New BMW leather interior door panels installed.
> Oil, filter, fluids.

2000-2001

> Service records for period not retained: periodic (approximately 5000 mile intervals) oil, filter, fluids service by local garage.

Feb 2000 – 62000 miles (approx)
> Purchased car from Concord Motorsports, Chichester NH with up to date service and fresh clutch.
> Original owner of car located in College Park PA.
