

DATE 3/31 CUSTOMER # M5

DC DIRECT LIST

QTY.	PART NUMBER	BRAND
✓	AC - Rechargeol	Mount Brakes
	Exhaust is very rusted / one hanger Tires are old / rears are wavy	
	Play in steering rack / idler box Front control arms	
✓	Sway bar links - front	
	Engie - some oil leak Engine mounts Oil level sensor shown in IC	
	Transmission some oil leak Transmission mounts	
✓	Brake fluid Some metal brake and fuel lines have corrosion	
	Rear sway bar links and bushings Rear control arm links	
	Corrosion on sever spots on under carriage	

Invoice



160 Wall Ct., Inman, SC 29349
Phone: (864) 248-3067

Name:	BMW Foundation	Repair Order #	0228
Street:	190 Manatee Ct.		
City:	Greer, SC 29651		
Phone:	1-864-438-2056		

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN
Black	1991	BMW M5	BK06320	MER886	177395
DEL. DATE	PROD. DATE	PROMISED	PAYMENT	R.O. OPENED	READY
	07/1991		Check/Cash	09/25/2020	09/29/2020

Parts	QUANTITY	LIST	NET	TOTAL
Brake Fluid	2	4.52		9.04
Radiator anti freeze	0.5			5.90
Brake cleaner	1			4.50
Hose clamp	1			3.50
Wind shield wash	0.5			2.50
Starter battery - Bosch	1			229.50
Front sway bar link	2	49.19		98.38
Parts				327.88
Sales Tax				22.95
Total Parts				350.83

JOB DESCRIPTION	HOURS	LIST	NET	TOTAL
Pre-delivery inspection.	1.0	85.00		85.00
Replace brake fluid – bleeder valves are damaged due to corrosion.	1.0	85.00		85.00
Replace hose clamp for fuel line.	0.5	85.00		42.50
Evacuate and charge A/C system including oil.				150.00
Check and top of fluids, inflate tires.	0.2	85.00		17.00
Remove and replace front sway bar links.	1.0	85.00		85.00
Total Labor				464.50
Total Parts				350.83
Total				815.33